


FIG. 1






FIG. 2




FIG. 3




FIG. 4




FIG. 5





FIG. 6

FIG. 7






FIG. 8





FIG. 9

10/24



11/24

FIG. 11




FIG. 12




FIG. 13





FIG. 14




FIG. 15

14/24




FIG. 17





FIG. 18






FIG. 19






FIG. 20



	TAP #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
		P															Mp							
38	SV#1	4	8	4	•	•	•	•	•	•	•	•	•	•	•	•	2	4	2	•	•	•	•	
40	SV#2	6	12	6	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	R ₁ ,T ₀	
42	SV#3	4	8	4	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	R ₂ ,T ₀	
44	SV#4	2	4	2	•	•	•	•	•	•	•	1	2	1	•	•	•	•	•	•	•	•	R ₃ ,T ₀	
		P															Mp						R ₄ ,T ₀	
		MAY BE TURNED OFF																						
		P															2 1/2 MI.	Mp						
38	SV#1	•	•	•	•	6	12	6	•	•	•	•	•	•	•	•	•	4	8	4	•	•	•	R ₁ ,T ₁
40	SV#2	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	6	12	6	•	•	•	R ₂ ,T ₁
42	SV#3	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	4	8	4	•	•	•	R ₃ ,T ₁
44	SV#4	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	2	4	2	•	•	•	R ₄ ,T ₁
		P																						
		CODE PHASE VERIFICATION																						
		P															2 MI.	Mp						
38	SV#1	•	•	•	•	6	12	6	•	•	•	•	•	•	•	•	4	8	4	•	•	•	•	R ₁ ,T ₂
38	SV#1	•	•	•	•	•	•	6	12	6	•	•	•	•	•	•	4	8	4	•	•	•	•	R ₁ ,T ₃
38	SV#1	•	•	•	•	•	•	6	12	6	•	•	•	•	•	•	1	1/2 MI.	Mp	8	•	•	•	R ₁ ,T ₄
38	SV#1	•	•	•	•	•	•	6	12	6	•	•	•	5	10	5	•	•	•	•	•	•	•	R ₁ ,T ₅
38	SV#1	•	•	•	•	•	•	6	12	6	5	10	5	•	•	•	3	•	•	•	•	•	•	R ₁ ,T ₆
		P?															1	MI.	Mp?					
		6	•	•	•	•	•	•	•	•	•	•	•	4	8	4	•	•	•	•	•	•	•	

FIG. 22

FIG. 23






FIG. 24




FIG. 25A




FIG. 25B

FIG. 26

24/24

